



NOTE:
MOTOR #2 ONLY
PROVIDED ON
SIZES 08, 10 & 12

Optional
PULL JP1 FOR UNIT MOUNTED REMOTE
TEMP SENSOR

Optional

LEGEND

- FIELD WIRED
- FACTORY WIRED
- FIELD CONNECTION
- FACT. CONNECTION
- + FACTORY WIRE – NOT CONNECTED
- WIRE TERMINATION

- NOTES:**
- COMPLETE THE WIRING IN ACCORDANCE WITH NATIONAL AND LOCAL CODES.
 - USE SOLID COPPER SUPPLY WIRES.
 - CONNECTOR LABEL MATCHES SUB-PANEL.
 - ONLY USE DIRECT REPLACEMENT COMPONENTS.
 - FIELD INSTALLED REMOTE TEMPERATURE SENSOR: WIRE TO THERMOSTAT TB1 TERMINALS 1 AND 2.
 - CONTROLLER SHIPPED LOOSE IF WALL MOUNTED.
 - CONTROL VALVE IS SHIPPED LOOSE.

CAUTION: NOT FOLLOWING
PROPER WIRING PROCEDURE
CAN CAUSE INJURY OR DEATH.

| | NAME | DATE |
|------------|------|----------|
| DRAWN BY | DH | 10/25/24 |
| MECH APPR. | -- | -- |
| ELEC APPR. | -- | -- |
| ENG APPR. | -- | -- |
| MFG APPR. | -- | -- |

zehnder Buffalo, NEW YORK

Rittling

| | | |
|--|--------------|------|
| DESCRIPTION | | |
| 2F0T PSC 3SPD 120/60/1 UMC TEMP CUH DRAWING | | |
| SIZE | PART NO. | REV. |
| B | 11D00035925A | A |
| SHEET 1 OF 1 | | |

PROPRIETARY AND CONFIDENTIAL
THE INFORMATION CONTAINED IN THIS
DRAWING IS THE SOLE PROPERTY OF
ZEHNDER. ANY REPRODUCTION IN PART
OR AS A WHOLE WITHOUT THE WRITTEN
PERMISSION OF ZEHNDER IS PROHIBITED.